

I

Cerniera in ferro a saldare grezza a 3 ali aperte con perno sfilabile con rondella grezza

UK

Black iron 3 open wing hinge with removable pin and ring to be welded

D

Schwarze Eisen Scharniere 3 offen. Fluegel mit ausziehbar. Stifte und Ring zum schweissen

F


Charnière fer brut 3 volets ouverts pivot dégonable à souder

E

Bisagra hierro negro 3 alas abiertas con pernio extraible y anilla para soldar

RUS

Петля черный металл с 3 открытыми площадками под сварку разъемная



Articolo - Article

Riferimento - Reference

137

EG 00 18 30



N°



4

4,2