

I **Pioli di fissaggio a saldare e avvitare per cremagliera art. 47**

UK

Fixing staves for rack 47

D

Befestigung zum schweissen oder schrauben fuer 47

F


Fixation à souder ou à visser pour crémaillere 47

E

Travesaño de fijación para cremallera 47 para soldar o atornillar

RUS

Крепеж под сварку или винты



Art. 48

avvitare - to screw
schrauben - à visser
atornillar - atornillar
завинчивать

Art. 49

saldare - to weld
zum schweißen - à souder
soldar - soldar
под сварку

Articolo - Article		Descrizione Description	L	L1	F		
Riferimento - Reference			mm			N°	
48	IZ 00 48 A0	Avvitare	25	10	M8	30	1,7
49	IZ 00 49 S0	Saldare	25	/	/	30	1,7